



N° DE INFORME  
CLIENTE  
HORMIGON TIPO  
VOLUMEN m3

1  
SANATORIO ARGENTINO  
H20  
5,5

**LABORATORIO H25 SRL**  
AV. SASTE Y CALLE 100 - FRONTERA - SANTA FE  
info@h25srl.com.ar  
Tel 3564-420300/434405

### ENSAYO DE COMPRESIÓN

| PROBETA<br>N° | FECHA INICIAL | FECHA DE ROTURA | EDAD | Kn     | Kg/cm2     | CORRECCION  | OBSERVACION |
|---------------|---------------|-----------------|------|--------|------------|-------------|-------------|
| 1             | 3-jul         | 13-jul          | 10   | 216,26 | 122,443664 | 162,6404807 |             |
| 2             | 3-jul         | 13-jul          | 10   | 217,85 | 123,343902 | 163,836256  |             |
| 3             | 3-jul         | 31-jul          | 28   | 315,72 | 178,756653 | 178,684873  |             |
| 4             | 3-jul         | 31-jul          | 28   | 291,03 | 164,777488 | 164,711322  |             |

ASENTEMIENTO 14CM